
NOTES


TABLE OF CONTENTS

| | | |
|------|--|---|
| 1.0 | Introduction | 2 |
| 2.0 | Calibration curves | 3 |
| 3.0 | Crude hectolitre appointment | 3 |
| 4.0 | Design of the device | 4 |
| 4.1 | Menu | |
| 4.2 | Keypad symbols | |
| 5.0 | Most common reasons for miss readings | 6 |
| 6.0 | Device maintenance instructions | 6 |
| 7.0 | Changing batteries | 7 |
| 8.0 | Determination of the material moisture | 7 |
| 9.0 | Technical data | 8 |
| 10.0 | Warranty | 9 |

1.0 INTRODUCTION

1. Put the measuring device on a flat surface.
2. Make sure that the measuring chamber is completely empty. It is important that no material is left in the measuring chamber when you turn on the device.




3. Switch on the humimeter FS1 by pressing the power button () for 3 sec.





4. As the next step, please do the self calibration. The word "calibrate" will show up on your display. Accept by pressing the button.



5. In case a menu point is shown, press the left button () until you reach the measuring window.



6. Select the right calibration curve for your material under test using the buttons  or .

7. Fill up the measuring device with the sample material. The filling needs to be done slowly and constantly to ensure reproducible results. The measuring chamber has to be filled up to the edge!!



Important:

Place the measuring device on a flat surface, or hold it in your hand vertically by the filling. The filling needs to be done slowly and constantly. DO NOT SHOVEL OUT OF THE BUNCH!!!

8. The display shows the measuring result.
9. Empty the humimeter and ensure that no grain rests are accumulated in the measuring chamber.



NOTES


NOTES

2.0 CALIBRATION CURVES

| Name of Calibration curve | Material under test | hectolitre | Measuring range |
|---------------------------|---------------------|------------|-----------------|
| 70 corn | corn | 70 | 10 up to 25% |
| corn 75 | corn | 75 | 10 up to 25% |
| 80 corn | corn | 80 | 10 up to 25% |
| rye | rye | | 10 up to 20% |
| 80 Whe/Tri | Weizen / Triticale | 70 | 10 up to 23% |
| Whe/Tri 75 | Weizen / Triticale | 75 | 10 up to 23% |
| 80 Whe/Tri | Weizen / Triticale | 80 | 10 up to 23% |
| 60 barley | barley | 60 | 10 up to 23% |
| barley 65 | barley | 65 | 10 up to 23% |
| 70 barley | barley | 70 | 10 up to 23% |
| oats 40 | oats | 40 | 10 up to 18% |
| 50 oats | oats | 50 | 10 up to 18% |
| rapese 65 | rapese | 65 | 5 up to 15% |
| soybean | soybean | | 8 up to 18% |
| sunflower | sunflower | | 8 up to 18% |
| horsebean | horsebean | | 5 up to 20% |
| rice peeled | rice peeled | | 9 up to 18% |
| reference | ----- | ----- | ----- |


- Reference: To test the humimeter FS1.
- Grey measuring values are no valid measurement values.

3.0 CRUDE HECTOLITRE APPOINTMENT



Put the empty device on the scale → turn on the scale → fill up the device with the material under test → discard at the edge of the measuring chamber → put the filled device on the scale → read out the value of the scale → select the right calibration curve.





4.0 DESIGN OF THE DEVICE



4.1 Menu

There are 2 menu levels.

The symbols show the key functions in the different menus.

1. Type Selection :    

To enter the second menu level you have to press the both arrow keys when you turn on the device

2. Main menu:
Options
Date / Time
Language
Unlock
°C / °F
Password
Reset
Materialcalib.
Status

10.0 WARRANTY

Electromatic Equipment Co., Inc. (Electromatic) warrants to the original purchaser that this product is of merchantable quality and confirms in kind and quality with the descriptions and specifications thereof. Product failure or malfunction arising out of any defect in workmanship or material in the product existing at the time of delivery thereof which manifests itself within one year from the sale of such product, shall be remedied by repair or replacement of such product, at Electromatic's option, except where unauthorized repair, disassembly, tampering, abuse or misapplication has taken place, as determined by Electromatic. All returns for warranty or non-warranty repairs and/or replacement must be authorized by Electromatic, in advance, with all repacking and shipping expenses to the address below to be borne by the purchaser.

THE FOREGOING WARRANTY'S IN LIEU OF ALL OTHER WARRANTY'S, EXPRESSED OR IMPLIED, INCLUDING BUT NOT LIMITED TO, THE WARRANTY OF MERCHANTABILITY AND FITNESS FOR ANY PARTICULAR PURPOSE OR APPLICATION. ELECTROMATIC SHALL NOT BE RESPONSIBLE NOR LIABLE FOR ANY CONSEQUENTIAL DAMAGE, OF ANY KIND OR NATURE, RESULTING FROM THE USE OF SUPPLIED EQUIPMENT, WHETHER SUCH DAMAGE OCCURS OR IS DISCOVERED BEFORE, UPON OR AFTER REPLACEMENT OR REPAIR, AND WHETHER OR NOT SUCH DAMAGE IS CAUSED BY MANUFACTURER'S OR SUPPLIER'S NEGLIGENCE WITHIN ONE YEAR FROM INVOICE DATE.

Some State jurisdictions or States do not allow the exclusion or limitation of incidental or consequential damages, so the above limitation may not apply to you. The duration of any implied warranty, including, without limitation, fitness for any particular purpose and merchantability with respect to this product, is limited to the duration of the foregoing warranty. Some states do not allow limitations on how long an implied warranty lasts but, notwithstanding, this warranty, in the absence of such limitations, shall extend for one year from the date of invoice.

Electromatic Equipment Co., Inc.
600 Oakland Ave. Cedarhurst, NY 11516 - USA
Tel: 1-800-645-7330 / Tel: 516-295-4300 / Fax: 516-295-4399





Every precaution has been taken in the preparation of this manual. Electromatic assumes no responsibility for errors or omissions. Neither is any liability assumed for damages resulting from the use of information contained herein. Any brand or product names mentioned herein are used for identification purposes only, and are trademarks or registered trademarks of their respective holders.

9.0 TECHNICAL DATA







| | |
|----------------------------------|--|
| Resolution of the display | 0,1% water content 0,5°C temperature |
| Measuring range | 5 up to 30 % |
| Operation temperature | 0°C up to 40°C |
| Storage temperature | -20°C up to 60°C |
| Temperature compensation | Automatically |
| Power supply | 4 pcs. 1.5 Volt AA Alkaline batteries (1800 measurements) |
| Auto Switch OFF | After app.5 minutes |
| Current consumption | 30 mA (with light) |
| Display | 128 x 64 matrix display (lighted) |
| Dimensions | 260 x 70 x 250 mm |
| Weight | app. 360 g (with batteries) |
| Degree of protection | IP 40 |
| Scope of supply | measuring device HMC-FS1 4 x 1.5Volt AA Alkaline Batteries |
| Optional accessories | Plastic case Digital scale 1000g Measuring cup 0.5 litre |

4.2 Keypad symbols

Measuring window:

-  : Power ON / OFF
-  : Switch upper
-  : Switch lower
-  : Hold

Menu:

-  : Enter
-  : Switch upper
-  : Switch lower
-  : Exit
-  : Yes
-  : No
- OK** : OK

5.0 MOST COMMON REASONS FOR MISS READINGS

- **Product temperature out of application range**

Material **below 0°C** resp. **above 40°C** (32 to 104 °F) may cause faulty measurements. The storage of cold material in a warm storage area usually creates condensed water which may lead to major measuring errors.

- **Not adjusted material**

Let your humimeter FS1 acclimate to the surrounding temperature of the material for approximately half an hour.

A very high temperature difference has a negative effect on the stability of the measurement result.

- **Wrong calibration curve**

Before you measure your sample, double check the correct selection of the calibration curve.

- **Wrong hectolitre range**

- **Wet or mouldy material**

- **Frozen measuring material.**

6.0 DEVICE MAINTENANCE INSTRUCTIONS

To provide a long lives of your device please do not expose it to strong mechanical loads or heat e.g. dropping it or direct sunlight exposure.

Clean your device using a **dry cloth**. The measuring chamber needs to be cleaned with a **dry and soft brush**.

Any kind of wet cleaning damages the device. The instrument is not rainproof. Keep it in dry areas.

We recommend an interval ISO-conforming device check with the drying method.

Electromatic will also provide for a fee a test with a calibration certificate.

7.0 CHANGING BATTERIES

Your new device is provided with batteries.

Changes the batteries:

1. Press with your finger onto the arrow of the battery cap and pull it back.
2. Remove the empty batteries.
3. Put four new batteries in the device. Make sure the position of the battery poles is correct.
4. Press down the batteries and close the cap.



8.0 DETERMINATION OF THE MATERIAL MOISTURE

The principle is a comparison measurement with the drying out method according to DIN 10350: 1967 09. Take the measured sample and weigh it. Dry it out in an oven and weigh it again. Following formula can be taken to determine the absolute moisture:

Note: The dried material may not be used any more for measuring purposes!

$$\%F = \frac{M_n - M_t}{M_n} \times 100$$

M_n : Mass with average moisture content

M_t : Mass of the dried sample

%F : Calculated absolute moisture

Exemption from liability

For miss-readings and wrong measurements and of this resulting damage we refuse any liability. This is a device for quick determination of moisture. The moisture depends on multiple conditions and multiple materials. Therefore we recommend a plausibility check of the measuring results. Each device includes a serial number and the guarantee stamp. If those are broken, no claims for guarantee can be made. In case of a faulty device, please contact Electromatic.

FS1

COMPACT GRAIN MOISTURE METER

