

TABLE OF CONTENTS


1.0	Design BL2 wood chips probe (art. no. 12518)	2
2.0	Measuring procedure BL2 wood chips probe	3
3.0	Calibration curves BL2 wood chips probe	4
4.0	Determination of the material reference moisture	4
5.0	Design BL2 hammer (art.no. 12520)	5
6.0	Measuring procedure BL2 hammer	6
7.0	Information for measurement with BLW hammer	7
8.0	Sort of wood (calibration curves) BL2 hammer	8
9.0	Design FLW tester (art. no. 12119)	9
10.0	Measuring procedure FLW tester	9
11.0	Calibration curves FLW tester	10
12.0	Menu level overview	11
13.0	Changing batteries	12
14.0	Running the instrument	13
15.0	List of calibration curves	13
16.0	Activation of the “super user” function	14
17.0	Changing the Userlevel	14
18.0	Device maintenance instructions	14
19.0	Transfer saved data to the PC	15
20.0	Print saved data	16
21.0	Technical data BL2 (Art. Nr. 12109)	17
22.0	Technical data BL2 wood chips probe (art. no. 12518)	17
23.0	Technical data BL2 hammer (art. no. 12520)	18
24.0	Technical data FLW tester (art. no. 12119)	18
25.0	Exemption from liability	18
26.0	Most common reasons for miss readings with BL2 hammer	19
27.0	Most common reasons for miss readings with FLW tester	19
28.0	Most common reasons for miss readings with BL2 wood chips probe	20
29.0	Warranty	21

1.0 DESIGN BL2 WOOD CHIPS PROBE (ART. NO. 12518)




2.0 MEASURING PROCEDURE BL2 WOOD CHIPS PROBE

1. For a correct measurement please ensure that the device has the same temperature than the wood chips (+/-3°C). For that reason, let your humimeter BL2 adjust to the surrounding temperature of the material for at least half an hour before measuring.

2. Switch on the device: Press the  key for three seconds.






3. Plug the probe of your BL2 wood chips probe **straight into the wood chips**. It is not allowed to load the measuring head incorrect or drop it down!








4. Plug in the sensor cable into the socket of the BL2. Take care of the correct position and fix it with the knurled nut.




5. Change the calibration curve: Press one time the  key and then the  or  key. The name of the calibration curve can be seen at the head of the display.



6. **Now the display shows the water content.** Left hand the temperature is displayed.

7. To save the results in the save menu press the  ( button). The storage was successful when the number in front of the symbol  increased. To reach the store menu please press  until the  appears.



8. To name the saved results press the  button.
9. Remove the BL2 probe straight with caution and clean the measuring head.

Risk of injury by measuring head!
Keep away from children!

3.0 CALIBRATION CURVES BL2 WOOD CHIPS PROBE

NOTES

Calibration curves	Declaration	Measuring range
Wood chips	Standard woodchips	10 - 50 %
Coarse chips	Coarse woodchips	10 - 50 %
Industrial chips	Industrial woodchips	10 - 50 %
Pellets	Pellets made of wood	11 - 20 %
Sawdust	Sawdust	14 - 50 %
Digit 2	For special product	
Empty 2	Customer calibration made by Checkline Europe	
Test block	<i>! Only for testing the BL2 with the test block !</i>	

- **Wood chips:** standard chips of wood (forest wood chips) according to EU-norm CEN/TS 14961 class **P16** and **P45**.
- **Coarse chips:** for coarse wood chips **P45 but with fewer fines**.
- **Industrial chips:** for industrial chips of wood **without barks and fines** (similar **P63**)

Definition of wood chips classes

The stated numbers refer to the particle size that goes through round gaps of the corresponding diametres (e.g. P16: 16 mm).

- **P16** minimum 80% of the bulk is between 3,15 and 16 mm
- **P45** minimum 80% of the bulk is between 3,15 and 45 mm
- **P63** minimum 80% of the bulk is between 3,15 and 63 mm

Compression of wood chips

The humimeter BL2 is calibrated for normally compressed wood chips. If the measured wood chips are compressed to a much lesser or greater extent, this will cause measuring imprecisions. Normally compressed wood chips are defined in norm CEN/TS 15103 (determination of the bulk density).

4.0 DETERMINATION OF THE MATERIAL REFERENCE MOISTURE


The principle is a comparison measurement with the dehydration method according to CEN/TS 14774. Take the measured sample and weigh it. Dry it out in an oven and weigh it again.

$$\% F = \frac{M_n - M_t}{M_n} \times 100$$











M_n : Mass with average moisture content
 M_t : Mass of the dried sample
 %F: Calculated moisture content

NOTES

5.0 DESIGN BL2 HAMMER (ART.NO. 12520)



6.0 MEASURING PROCEDURE BL2 HAMMER

1. For a correct measurement please ensure that the device has the same temperature than the wood (+/- 3°C). For that reason, let your humimeter BL2 hammer adjust to the surrounding temperature of the material for at least half an hour before measuring.
2. Switch on the device: Press the  key for three seconds.
3. Choose a part of the wood, **WITHOUT bark, branches, pitch pockets or cracks** and drive the ram electrode in the right angle to the grain into the wood. Hold the top of the electrode with one hand, take the handhold with the other hand and push down the handhold with active force. Drive the nails about 2 cm deep into the wood.
Attention: Risk of injury!!!
4. Plug in the sensor cable into the socket of the BL2. Take care of the correct position and fix it with the knurled nut.
5. Change the calibration curve: Press one time the  key and then the  or  key. The name of the calibration curve can be seen at the head of the display.
6. **Now the display shows the water content.** Left hand the temperature is displayed.
7. To save the results in the save menu press the  ( button). The storage was successful when the number in front of the symbol  increased. To reach the store menu please press  until the  appears.
8. To name the saved results press the  button.
9. Push out the ram electrode of the wood with caution.



NOTES

29.0 WARRANTY

Electromatic Equipment Co., Inc. (Electromatic) warrants to the original purchaser that this product is of merchantable quality and confirms in kind and quality with the descriptions and specifications thereof. Product failure or malfunction arising out of any defect in workmanship or material in the product existing at the time of delivery thereof which manifests itself within one year from the sale of such product, shall be remedied by repair or replacement of such product, at Electromatic's option, except where unauthorized repair, disassembly, tampering, abuse or misapplication has taken place, as determined by Electromatic. All returns for warranty or non-warranty repairs and/or replacement must be authorized by Electromatic, in advance, with all repacking and shipping expenses to the address below to be borne by the purchaser.

THE FOREGOING WARRANTY'S IN LIEU OF ALL OTHER WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING BUT NOT LIMITED TO, THE WARRANTY OF MERCHANTABILITY AND FITNESS FOR ANY PARTICULAR PURPOSE OR APPLICATION. ELECTROMATIC SHALL NOT BE RESPONSIBLE NOR LIABLE FOR ANY CONSEQUENTIAL DAMAGE, OF ANY KIND OR NATURE, RESULTING FROM THE USE OF SUPPLIED EQUIPMENT, WHETHER SUCH DAMAGE OCCURS OR IS DISCOVERED BEFORE, UPON OR AFTER REPLACEMENT OR REPAIR, AND WHETHER OR NOT SUCH DAMAGE IS CAUSED BY MANUFACTURER'S OR SUPPLIER'S NEGLIGENCE WITHIN ONE YEAR FROM INVOICE DATE.

Some State jurisdictions or States do not allow the exclusion or limitation of incidental or consequential damages, so the above limitation may not apply to you. The duration of any implied warranty, including, without limitation, fitness for any particular purpose and merchantability with respect to this product, is limited to the duration of the foregoing warranty. Some states do not allow limitations on how long an implied warranty lasts but, notwithstanding, this warranty, in the absence of such limitations, shall extend for one year from the date of invoice.

Electromatic Equipment Co., Inc.
600 Oakland Ave. Cedarhurst, NY 11516 - USA
Tel: 1-800-645-7330 / Tel: 516-295-4300 / Fax: 516-295-4399

Every precaution has been taken in the preparation of this manual. Electromatic assumes no responsibility for errors or omissions. Neither is any liability assumed for damages resulting from the use of information contained herein. Any brand or product names mentioned herein are used for identification purposes only, and are trademarks or registered trademarks of their respective holders.

7.0 INFORMATION FOR MEASUREMENT WITH BLW HAMMER

- With the standard nails the wettest part over the whole measuring depth will be measured. If you need the water content in a defined measuring depth, you should use the isolated green nails (article number 11426), because they are only measuring at the points.
- Important: You have to remove the bark before you can start to measure.
- The measuring depth should be a quarter of the wood diameter. In the worst case you have to cut away a part of the diameter.
- Statistically, the spot that shows best the average moisture of the wood is at about 20% of the total wood length.
- Take a few logs on different positions of each piece of wood you intend to measure, and the humimeter BL2 will calculate automatically the average value of the series.
- The measure value which is shown at the display of your humimeter BL2, represents the "water content" of the wood. So there is no conversion from the "wood moisture" into "water content" for use. It is also possible to change the value into "wood moisture". If you need this, contact us.
- Definition water content:
The water content is declared as the amount of water in a wood, which stands in relationship to the whole weight of the wood. For example: You have 1kg Wood with 40% water content; the wood consist of 0,4kg water and 0,6kg wood.
- Definition wood moisture:
The wood moisture is declared as the amount of water in a wood, which stands in relationship to the weight of the dried wood. The same example: You have 0,6kg Wood with 0,4kg water; the 0,6kg wood represents 100%, so the 0,4kg water will be 66,7% wood moisture.

8.0 SORT OF WOOD (CALIBRATION CURVES) BL2 HAMMER

Main Group	Sub groups							
Beech	Rubber							
Oak	Mahogany	Wenge						
Alder	Acacia	Alstonia	Birch	European chestnut	Horse chestnut	Cherry Tree	Walnut	Okan
Ash	Keruing							
Spruce								
Pine	Balsa	Yew Tree	Stone Pine					
Larch	Maple	Douglas Fir	Hemlock	Cotton Wood	Elm			
Fir	Ceiba	Linden						
Willow	Pear	Hickory	Olive wood	Ramin	Teak			

Declaration: The main group of wood is the wood sort, which is shown on the measurement display of your humimeter BL2. Do you want to measure wood, which is not in the list of the main group, you should search it at the sub groups in the table above. Then use the wood of the main group for the measuring. For example: If you want to measure "Cherry Tree", you have to choose the "Alder" wood at you device.

Valid measuring Range

Beech	32%
Oak	32%
Alder	40%
Ash	35%
Spruce	40%
Pine	35%
Larch	32%
Fir	37%
Willow	40%

If the measure value is grey, the standard valid measuring range is exceeded (limits see Table). In this case the accuracy will be decreasing.

A blinking measuring value shows you the upper end of the measuring range.



28.0 MOST COMMON REASONS FOR MISS READINGS WITH BL2 WOOD CHIPS PROBE

- **Product temperature out of application range**

Material below 0°C resp. above +40°C (32 to 104 °F) may cause faulty measurements.

- **Temperature difference between meter and sample**

Please ensure that the device and the material under test are being stored at the same temperature (+/-3°C) before measuring. A high temperature difference has a negative effect on the stability of the measurement results.

- **Wrong calibration curve**

Before you measure your sample, double check the correct selection of the calibration curve.

- **Wet or mouldy material**


If you measure such products, the accuracy will decrease.

- **Frozen wood chips**

- **Water film at the measuring head**


After measuring wet material a water film can arise on the sensor head. This could lead to a too high result in the following measurement. After measuring wet material clean both black plastic parts accurately with a dry cloth.

It is not allowed to load the measuring head incorrect (stress, bending), other wise it can be broken. Plug and remove the insertion probe of your BL2 wood chips probe straight into the wood chips.



Do not move the BL2 probe crosswise to the insertion direction after plugging in.

Do not drop the measuring head or use it for any ulterior purposes.



A broken measuring head is no case of warranty!

26.0 MOST COMMON REASONS FOR MISS READINGS WITH BL2 HAMMER

- **Product temperature out of application range**

Material below 0°C resp. above +50°C (32 to 122 °F) may cause faulty measurements.

- **Temperature difference between meter and sample**

Please ensure that the device and the material under test are being stored at the same temperature (+/-3°C) before measuring. A high temperature difference has a negative effect on the stability of the measurement results.

- **Wrong calibration curve**

Before you measure your sample, double check the correct selection of the calibration curve.

- **Frozen wood or beetle infested wood**

If you measure such products, the accuracy will decrease.

- **Measurement through bark**

In fact of that the accuracy will decrease.

- **Direct solar radiation**

27.0 MOST COMMON REASONS FOR MISS READINGS WITH FLW TESTER

- **Product temperature out of application range**

Material below 0°C resp. above +40°C (32 to 104 °F) may cause faulty measurements.


- **Temperature difference between meter and sample**

Please ensure that the device and the material under test are being stored at the same temperature (+/-3°C) before measuring. A high temperature difference has a negative effect on the stability of the measurement results.


- **Water film at the measuring head**

After measuring wet material a water film can arise on the sensor head. This could lead to a too high result in the following measurement. After measuring wet material clean both black plastic parts accurately with a dry cloth.

9.0 DESIGN FLW TESTER (ART. NO. 12119)




10.0 MEASURING PROCEDURE FLW TESTER

1. For a correct measurement please ensure that the device has the same temperature than the material (+/-3°C). For that reason, let your FLW tester adjust to the surrounding temperature of the material before measuring.
2. Switch on the device: Press the  key for three seconds.






3. Plug the probe of your FLW tester **straight into the material**. It is not allowed to load the measuring head incorrect or drop it down!



4. Plug in the sensor cable into the socket of the BL2. Take care of the correct position and fix it with the knurled nut.









5. Change the calibration curve: Press one time the  key and then the  or  key. The name of the calibration curve can be seen at the head of the display.



6. **Now the display shows the water content.** Left hand the temperature is displayed.



7. To save the results in the save menu press the  ( button). The storage was successful when the number in front of the symbol  increased. To reach the store menu please press  until the  appears.

8. To name the saved results press the  button.

9. Remove the FLW tester straight with caution and clean the measuring head.

Risk of injury by measuring head!
Keep away from children!

and the guarantee stamp. If those are broken, no claims for guarantee can be made. In case of a faulty device, please contact Checkline Europe.

11.0 CALIBRATION CURVES FLW TESTER

Calibration curve	Material
Digit 3	For special product
Empty 3	Customer calibration made by Checkline Europe
Test block	<i>! Only for testing the BL2 with the test block !</i>

23.0 TECHNICAL DATA BL2 HAMMER (ART. NO. 12520)

Resolution of display	0.1% water content 0.5°C temperature
Measuring range	8% to 60% water content
Operation temperature	0°C to +50°C
Temperature measuring range	-10°C to +60°C
Dimension	360 x 45 x 45 mm
Weight	1500 g
Protection class	IP 40
Option	Replacement tips 60mm insulated, measuring tips set 255mm for bales of hay- and straw (art. no. 12521)


24.0 TECHNICAL DATA FLW TESTER (ART. NO. 12119)

Resolution of display	0.1% water content 0.5°C temperature
Measuring range	depending of the material
Operation temperature	0°C to +40°C
Temperature measuring range	-10°C to +60°C
Dimension	1150 x 35 x 35 mm
Gewicht	530 g
Protection class	IP 40

25.0 EXEMPTION FROM LIABILITY

For miss-readings and wrong measurements and of this resulting damage we refuse any liability. This is a device for quick determination of moisture. The moisture depends on multiple conditions and multiple materials. Therefore we recommend a plausibility check of the measuring results. Each device includes a serial number

12.0 MENU LEVEL OVERVIEW




<i>Edit Logs</i>	<i>Options</i>
Manual Logs	Date / Time
Clear Logs	Log Time
<i>Print Logs</i>	Language
Last Log	Unlock
All Logs	°C / °F
Clear Logs	o Userlevel
<i>Send Logs</i>	BL On Time
Manual Logs	Auto Off Time
Clear Logs	Materialcalib.
<i>Options</i>	Password
<i>Status</i>	Reset



13.0 CHANGING BATTERIES

Please find enclosed the manual for changing of batteries:

1. At first remove the rubber protective housing. For that, hold the rubber housing at the upper side and pull it over. If your BL2 is provided with an optional USB port, you have to remove the protection cap before.
2. Press with your finger onto the arrow of the battery cap und pull it back.
3. Remove the empty batteries.
4. Put four new batteries in the device. Make sure that the positions of the battery poles are correct.
5. Press down the batteries and close the cap.



If the battery symbol appears in the measuring window resp. if a critical charge of battery is shown in the status, the batteries have to be changed IMMEDIATELY. If you do not use your humimeter device for a longer period, remove the batteries. For eventual resulting damages we cannot provide any warranty.



21.0 TECHNICAL DATA BL2 (Art. Nr. 12109)

Operation temperature	0°C to +50°C
Storage temperature	-20°C to +60°C
Temperature compensation	Automatically
Data logger	Approximately 10.000 values
Menu languages	German, English, French, Italian, Spanish, Russian
Power supply	4 pcs. 1.5 Volt AA Alkaline batteries (900 measurements)
Auto Switch OFF	After approx. 4 minutes
Current consumption	60mA (with light)
Display	128x64 matrix display, lighted
Dimension	150 x 75 x 30 mm
Weight	270 g (with batteries)
Protection class	IP 40
Scope of supply	Humimeter BL2, 4 x 1.5Volt AA Alkaline batteries rubber protective housing
Options	Wooden case for BL2, test block, humimeter USB-data interface modul, portable thermo-printer


22.0 TECHNICAL DATA BL2 WOOD CHIPS PROBE (ART. NO. 12518)

Resolution of display	0.5% water content 0.5°C temperature
Measuring range	10% to 50% water content
Operation temperature	0°C to +40°C
Temperature measuring range	-10°C to +80°C
Dimension	1150 x 35 x 35 mm
Weight	710 g
Protection class	IP 40

20.0 PRINT SAVED DATA

(Only possible with humimeter USB interface module in combination with Schaller thermo printer)

To print your saved data, connect the device to the printer using the printer cable that was delivered with your device. Carefully loose the protection cap on the humimeter BL2. At first plug in the side of the connector with the close plastic casing at the humimeter BL2. Then switch on the device.



Not till then the other side of the cable has to be plugged in at the printer. Switch on the printer by pressing . Now the green LED is blinking. If it does not blink, please change the batteries and try again.



Press the button at your humimeter until you reach the menu (see image on the right). Choose „Print Logs“ and confirm by pressing .



Now you can select if you want to print the last saved measuring series or all saved measuring series (logs).



Confirm by pressing again. The selected logs are printed out now.



To save paper, please think of clearing the data storage regularly.

14.0 RUNNING THE INSTRUMENT

Switch on: Press the key for three seconds

Set the clock: Press three times the key -> Options -> Date/Time

Save measuring value: Save the measuring value by pressing the button below the symbol. The storage was successful when the number in front of the symbol increased. To name the saved results press the button.

Hold measuring value: At first activate the function in the menu Options -> Datalog time by choosing "Hold". Then press the left key until appears. Press the key. The measuring value remains on the display until another button is pressed.

Display lighting: Press the key; Backlight will turn off automatically after 30 seconds. Backlight will be activated by pressing any key.


Power off: Press the key for five seconds; the device will be switched off when you leave the key. The device also switches off automatically when no key is pressed for four minutes.

Measuring range limit: If the measuring value is blinking, the valid measuring range is exceeded. In this case the accuracy will be decreasing.





15.0 LIST OF CALIBRATION CURVES

Pressing the or key in the measuring for at least three seconds and a list with all available sorts will appear. Select your sort by pressing or and confirm it with the key. The measurement will continue automatically.



16.0 ACTIVATION OF THE “SUPER USER” FUNCTION



Two times  - *Options* – Unlock

Enter the 4-digit password by using the  button (standard is the 4-digit serial number) and confirm by pressing the  button.



17.0 CHANGING THE USERLEVEL


Changing from advanced user to single user:

Make sure that you have activated the “super user” functions according to the instructions above. Afterwards change to the menu and choose „Options“.

In the submenu please select „o Userlevel“ (two times  – *Options* – o *Userlevel*)
Confirm by pressing the  button. Now the single user is activated.

Changing from single user to advanced user:

Keep both the buttons  and  pressed directly after switching on the device. Your humimeter automatically starts the main menu. Activate the the “super user” functions according to the instructions above.

Navigate to “*Options* – o *Userlevel*” and confirm by pressing the  button.

18.0 DEVICE MAINTENANCE INSTRUCTIONS

To provide a long life of your device please does not expose it to strong mechanical loads or heat e.g. dropping it or direct sunlight exposure. Clean your device using a dry cloth. Any kind of wet cleaning damages the device.

It is not allowed to load the measuring head incorrect (stress, bending), other wise it can be broken. Plug and remove the insertion probe of your BL2 straight into the wood chips.

The instrument is not rainproof. Keep it in dry areas. When the device isn't used for a longer period (2 months) or when the batteries are empty, they should be removed to prevent a leakage of the battery acid.




19.0 TRANSFER SAVED DATA TO THE PC

(Only possible with humimeter USB interface module)

To send your saved logs to the PC, connect the humimeter device to your PC using the USB cable that was delivered with your device. Carefully loose the protection cap on your humimeter and plug in the USB mini B connector. The bigger connector has to be connected to a USB slot on your PC. Start the LogMemorizer software on your PC and switch on your humimeter BL2.

The data transfer can be started on your humimeter or on the software.

Starting the data transfer on the humimeter:

Press the  key until you reach the menu (see image on the right). Then choose „Send Logs“ and confirm by pressing the  key. Now choose „Manual Logs“ and confirm with  again. All saved logs will be sent to your PC.



Starting the data transfer on your PC:

Press the button „remote control“ in the LogMemorizer software. A drop-down menu with several options opens (see image below).

For transferring the data you can select „Import last manual log“ (the last saved measuring series is transferred) or „Import all manual logs“ (all saved logs are transferred).

If you click on one of these menu items, the transfer starts immediately.

For the basic adjustments of the software please look through the instructions on the LogMemorizer CD.



BL2

UNIVERSAL BIOMASS MOISTURE METER

